

C.L. "BUTCH" OTTER - Governor RICHARD M, ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

January 18, 2007

Rebecca Skala, Administrator Hayden View Cottage, LLC PO Box 338 Athol, ID 83801

License #: RC-814

Dear Ms.. Skala:

On November 28, 2006, a life safety code survey was conducted at Hayden View Cottage, LLC. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Chris Laumann, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

CHRIS LAUMANN

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

CL/slc

JAMES E. RISCH - Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

December 12, 2006

Rebecca Skala, Administrator Hayden View Cottage, LLC PO Box 338 Athol, ID 83801

Dear Ms.. Skala:

On November 28, 2006, a life safety code survey was conducted at Hayden View Cottage, LLC. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by December 28, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

(X3) DATE SURVEY

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES

(X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED **IDENTIFICATION NUMBER:** 01 - BUILDING 1 A. BUILDING B. WING 13R814 11/28/2006 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 1921 EAST HAYDEN VIEW DRIVE HAYDEN VIEW COTTAGE, LLC COEUR D ALENE, ID 83815 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE (X4) ID (EACH DEFICIENCY MUST BE PRECEEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE PREFIX PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) DATE TAG TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on November 28, 2006. The surveyor conducting the survey was: Chris Laumann Health Facility Surveyor Facility Fire safety & Construction Bureau of Facility Standards TITLE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

(X6) DATE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

Facility Name		Physical Address	Phone Number		
Hayden View	J Gttoge.	1921 Hoyden View Dr. 1	208)763	5-8119	,
Administrator		l . *	ZIP Code		
Rebecca Skala		Survey Type	93815		
Survey Team Leader		Survey Type	Survey Date		
Chris Laumann		Fire Life Safety,	11/28/06		
NON-CORE ISSUES					
ITEM RULE# # 16.03.22		DESCRIPTION		DATE RESOLVED	BFS USE
1. 405.01.B	Extension cords: Ext	ension cords were found in 6	2m. 3		25 sept (64) 26 sept (64)
	Fournmy a kettle and	Televisian. A multiplus adant	orwas		
	tound in the same room powering a light and Clock. Another				100
	extension cord was found in Rm 2 powers miscelanous				0.00
	appliances. Another extension cord was found in the Living roun				
Howering the relevision and various television components. The					
ast was found powering a light in the exterior (rear) Sinder					80873
	area.				\$1.5×61
41	'				
2 410,01	Written Areement for	relocation round not be f	bare		6-8-9
F	at the time of survey.				
					50.00.00
					60 86 80

Response Required Date	Signature of Facility Representative			Date Signed	
12/26/61	Rebecca I Sk	ale	***************************************		